


# NI8-G18-ADZ30X2-B3331/S34 Inductive Sensor – Resistant to Magnetic Fields




### Technical data

Туре	NI8-G18-ADZ30X2-B3331/S34
ID	42091
Special version	S34 Corresponds to:Weld-field immune proximity sensors
General data	
Rated switching distance	8 mm
Mounting conditions	Non-flush
Secured operating distance	≤ (0.81 × Sn) mm
Correction factors	St37 = 1; Al = 0.3; stainless steel = 0.7; Ms = 0.4
Repeat accuracy	≤ 2 % of full scale
Temperature drift	≤ ±10 %
Hysteresis	315 %
Electrical data	
Operating voltage U <sub>B</sub>	20250 VAC
Operating voltage U <sub>B</sub>	10300 VDC
AC rated operational current	≤ 400 mA
DC rated operating current I <sub>e</sub>	≤ 300 mA
Frequency	≥ 50≤ 60 Hz
Residual current	≤ 1.7 mA
Isolation test voltage	1.5 kV
Surge current	≤ 3 A (≤ 20 ms max. 5 Hz)
Short-circuit protection	yes/Latching
Voltage drop at I <sub>e</sub>	≤ 6 V
Wire break/reverse polarity protection	yes/Complete

#### **Features**


- ■Threaded barrel, M18 x 1
- Chrome-plated brass
- ■AC 2-wire, 20...250 VAC
- ■DC 2-wire, 10...300 VDC
- ■NO contact
- ■1/2" male connector

## Wiring diagram



# Functional principle

Inductive sensors detect metal objects contactless and wear-free. For this, they use a high-frequency electromagnetic AC field that interacts with the target. Inductive sensors generate this field via an RLC circuit with a ferrite coil.






# Technical data

Output function	2-wire, NO contact, 2-wire
Smallest operating current	≥ 3 mA
Switching frequency	0.02 kHz
Mechanical data	
Design	Threaded barrel, M18 x 1
Dimensions	71 mm
Housing material	Metal, CuZn, Chrome-plated
Active area material	Plastic, PA12-GF30
Max. tightening torque of housing nut	25 Nm
Electrical connection	Connector, 1/2"
Environmental conditions	
Ambient temperature	-25+70 °C
Vibration resistance	55 Hz (1 mm)
Shock resistance	30 g (11 ms)
Protection class	IP67
MTTF	2283 years acc. to SN 29500 (Ed. 99) 40 °C
Power-on indication	LED, Green
Switching state	LED, Red

2|3

# Mounting instructions

#### Mounting instructions/Description




N N N N N N N N N N N N N N N N N N N

Distance D	3 x B
Distance W	3 x Sn
Distance T	3 x B
Distance S	1.5 x B
Distance G	6 x Sn
Distance N	2 x Sn
Diameter active area B	Ø 18 mm

### Accessories

MW18 6945004




Mounting bracket for threaded barrel sensors; material: Stainless steel A2 1.4301 (AISI 304)



6901320

Mounting clamp for smooth and threaded barrel sensors; material: Polypropylene



QM-18 6945102



Quick-mount bracket with dead-stop; material: Chrome-plated brass. Male thread M24 × 1.5. Note: The switching distance of the proximity switches may change when using quick-mount brackets.